Job #195508618

A Service (Appt 195508618-1)

Date

2026-09-27

Technician's Name

Kaleb Mayernick

Customer's Name

Andy Francis

Customer's Service Address


9 Monica Drive, Little Rock, AR 72204 USA

Is Customer without air or heat now?

System is Operational

Outdoor Unit Model and Serial

If there is no equipment information logged in the customer's record, PLEASE, enter info (pictures of the data tags are appreciated)



Picture of Gauges / Gas Pressure



Indoor Unit Model and Serial

If there is no equipment information logged in the customer's record, PLEASE, enter info (pictures of the data tags are appreciated)



Coil/ Heat Strips Model and Serial

If there is no equipment information logged in the customer's record, PLEASE, enter info (pictures of the data tags are appreciated)



Thermostat

If there is no equipment information logged in the customer's record, PLEASE, enter info (pictures of the data tags are appreciated)



Type of System

Furnace

System Location

Attic Horizontal

Do Parts need to be ordered? If yes, please describe part

X

Description of Work Performed

Returned to install double wall vent pipe. Removed single wall vent pipe. Installed double wall vent pipe and routed directly to roof penetration. Checked all connections and strapped vent pipe to ensure secureness. Vent pipe is venting and furnace of operating properly at this time.


Additional Notes


-

Repair Photos/ Before and After Repair

Please provide before and after pictures if repair was completed during service call













Recommended Add Ons

Recommended Add Ons

Recommended Add Ons

- [x] Preventative Maintenance